

GREG BELL Licutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA

Division Director

Representativ	es Present During the Inspection:
Company	Gregg Galecki
OGM	Karl Houskeeper



Inspection Report

Permit Number:	C0070005			
Inspection Type:	PARTIAL			
Inspection Date:	Wednesday, August 04, 2010			
Start Date/Time:	8/4/2010 7:30:00 AM			
End Date/Time:	8/4/2010 12:00:00 PM			
Last Inspection:	Monday, July 12, 2010			

Inspector: Karl Houskeeper,

Weather: Partly Cloudy, Temp. 69 Deg. F.

InspectionID Report Number: 2446

Accepted by: jhelfric

8/5/2010

Permitee: CANYON FUEL COMPANY Operator: CANYON FUEL COMPANY

Site: SKYLINE MINE

Address: HC 35 BOX 380, HELPER UT 84526

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Acreages

Total Permitted	11,064.00
Total Disturbed	121.97
Phase I	
Phase II	
Phase III	

Mineral Ownership

Other

Types of Operations

✓ Federal ✓ Underground **✓** State ☐ Surface County ☐ Loadout ✓ Fee Processing


Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

			•	-	
ıns	pecto	r's	Siar	าatu	re:

Date

Wednesday, Aug







Permit Number: C0070005 Inspection Type: PARTIAL

Inspection Date: Wednesday, August 04, 2010

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale				
2.	Signs and Markers	✓		✓	
3.	Topsoil				
4.a	Hydrologic Balance: Diversions	✓		✓	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	✓		✓	
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments	✓		✓	
8.	Noncoal Waste	✓		V	
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.8	a Roads: Construction, Maintenance, Surfacing				
16.	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Permit Number: C0070005 Inspection Type: PARTIAL

Inspection Date: Wednesday, August 04, 2010

Page 3 of 3

2. Signs and Markers

The mine identification signs are located at points of public access into the permit area. The signs contain the required information.

4.a Hydrologic Balance: Diversions

The rock has been removed from the diversion adjacent to the load out.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

The main sediment pond is currently being cleaned. Material from the cleaning is being hauled to the refuse pile. Water normally flowing into the pond is being diverted underground as approved in the MRP.

7. Coal Mine Waste, Refuse Piles, Impoundments

Material from the sediment pond cleaning at the main facilities is being placed into cells to allow the material to dry out.

8. Noncoal Waste

Items of noncoal waste were observed in the diversion adjacent to the explosive storage units. Items are to be collected and placed in an approved storage facility.